

Figure 1. Existing conditions at RPLA site, looking south



Figure 2. South boundary of RPLA, looking east. Drainage off-site is to canyons and slopes like the one to the right.



Figure 3. Looking west (downstream) along current Trabuco Creek Road and site of new lower access road. Creek channel to the right.



Figure 4. View south of Arroyo Trabuco from RPLA site. Existing crossing.



Figure 5. Looking upstream at site of current creek crossing and proposed culvert location.



Figure 6. Looking downstream from low point of crossing. North floodplain is constricted by cliffs. Upper access road will traverse hillside to the right.

